

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY REGION 5 77 WEST JACKSON BOULEVARD CHICAGO, ILLINOIS 60604

REPLY TO THE ATTENTION OF.

VIA ELECTRONIC AND CERTIFIED MAIL

April 8, 2008

Jennifer Hale Weyerhaeuser Company Environment Health & Safety, WTC 2G2 P.O. Box 9777 Federal Way, WA 98063-9777 EPA Region 5 Records Ctr.

RE: Plainwell Mill, Operable Unit #7, Allied Paper/Portage Creek/Kalamazoo River Site Work Plan Addendum to Investigate Source of Oily Sheen

Dear Ms. Hale:

I am writing in response to your letter of March 27, 2008 to the United States Environmental Protection Agency (EPA). Your letter responds to various comments provided by EPA to Weyerhaeuser Company (Weyerhaeuser) regarding a draft work plan addendum, which specifies those preliminary tasks necessary to investigate the source of an oily sheen observed while the company was conducting emergency response work on the mill banks.

With regard to the proper designation of the addendum, EPA now agrees with Weyerhaeuser that the document should be characterized as Addendum 1 to the draft RI/FS Work Plan, which is currently here in Region 5's office under review. EPA's conclusion is based on the definitions of (1) "Mill or "Mill Property"; and (2) "Mill Remedial Investigation and Feasibility Study" or "Mill RI/FS" in the Consent Decree for the Design and Implementation of Certain Response Action at Operable Unit 4 and the Plainwell Inc Mill Property of the Allied Paper/Portage Creek/Kalamazoo River Site (Civil Action No. 1:05 CV0003, February 15, 2005) (CD). In relevant part, the Mill RI/FS is defined as "those activities to be undertaken by Weyerhaeuser to assess the nature and extent of contamination at the Mill..." The Mill is defined by reference to Appendix H of the CD, which is a legal description of the property. The legal description includes that part of the real property between the top of the river banks and the Kalamazoo River. Although we do not currently know whether the source of the oily sheen is located on the river banks or between the banks and the Mill buildings, under either scenario the investigation would fall within the agreed scope of the Mill RI/FS. Accordingly, EPA agrees that this work is properly characterized as RI/FS work.

As such, EPA agrees that the response costs to be incurred and paid by Weyerhaeuser in connection with the activities described in the work plan are within the scope of the term "Allowable Costs" under paragraph 12 of the CD, and are eligible for

reimbursement according to the procedures and milestones for phased disbursement set forth in Appendix G to the CD.

Finally, EPA is conditionally approving Addendum 1 to the draft RI/FS Work Plan, with final approval pending EPA's receipt of a final version of the document that incorporates the revisions proposed in Weyerhaeuser's letter of March 27, 2008 and this letter.

Thank you for your attention to this matter. Please do not hesitate to call me at 312.886.1434, should you have any questions related to the project.

Sincerely,

Sam Chummar, Remedial Project Manager

U.S. EPA Region 5

CC:

James Saric, SR-6J Michael Berkoff, SR-6J Paul Bucholtz, MDEQ Eileen Furey, C-14J



SENDER: COMPLETE THIS SECTION	COMPLETE THIS SECTION ON DELIVERY
 Complete items 1, 2, and 3. Also complete item 4 if Restricted Delivery is desired. Print your name and address on the reverse so that we can return the card to you. Attach this card to the back of the mailpiece, or on the front if space permits. Article Addressed to: 	A. Received by (Please Print Clearly) C. Signature Agent Addressee D. Is delivery address different from item 1? Yes If YES, enter delivery address below: No
Jennifer Hale Weyerhaeuser Company	
Environment Health & Safety WTC 2G2 P.O. Box 9777 Federal Way, WA 98063-9777	L
	3. Service Type
	☑ Certified Mail ☐ Express Mail ☐ Registered ☐ Return Receipt for Merchandise
	☐ Insured Mail ☐ C.O.D.
	4. Restricted Delivery? (Extra Fee)
2. Article Number 7001 032	0 0006 1447 1769
(Transfer from service label)	CKER AT TOP OF ENVELOPE TO THE RIGHT

Domestic Return Receipt

102595-01-M-1424

PS Form 3811, March 2001